

Collection No. 12785 6 Designs

STITCH 'N' TURN MINI CHRISTMAS STOCKINGS



It is a violation of Copyright law to make and distribute copies of electronic designs or artwork. Electronic designs are licensed to the original purchaser for use at one location. ©2018 OESD, LLC. All rights reserved.





Isacord Thread Colors

0015 White 0532 Champagne 1900 Geranium 3761 Winter Sky 5531 Pear 5740 Mint

Note: One spool of 1000 meter thread is adequate for the project unless otherwise noted.

COLLECTION SUPPLIES

Stabilizers

- OESD AquaMesh WashAway
- OESD Fusible Woven

Fabrics/Textiles

- Quilter's Cotton Assorted Colors
- For each stocking: Back Panel – 14"x 6" folded wrong sides together to be 7"x 6" Front Panel – 6" x 6" (not folded)

Notions & Tools

- OESD Expert Embroidery Tape TearAway
- OESD Grippy Grid
- OESD Perfect Embroidery Press Cloth
- OESD Expert Point and Press Tool
- Embroidery Needle Sharp 75/11

Isacord Thread Colors

• Per thread chart

PREMIER

- SE





12785-01 12785-02 12785-03 **Requires 1 Design Requires 1 Design** Requires 1 Design 12785-04 12785-05 12785-06 **Requires 1 Design Requires 1 Design** Requires 1 Design




Notes

The project instructions included in the collection are general instructions. For demonstration purposes, a sample design that best demonstrates the technique is shown. Fabric and thread requirements will vary by design, but the general technique is the same.

Note: Some thread colors in instructions have been changed or digitally enhanced for better visibility.

- Cut one piece of Fusible Woven 7" x 6" and one piece 6" x 6".
- Apply one layer of Fusible Woven to the wrong side of each piece of fabric.
 Note: The 7" x 6" Fusible Woven will only cover one half of the fabric.
- Hoop two layers of AquaMesh for all designs.








STEP 2

- Load the selected design into the machine.
- Example design is 12785-05.
- Thread the machine per the thread chart.
- Place the hoop on the machine.
- Stitch Machine Step 1, Front Fabric Placement Stitch.




STEP 3

- Remove the hoop from the machine, but NOT the project from the hoop.
- Place the hoop on a flat surface.
- Completely cover the placement stitch with the front panel fabric.
- Tape in place to secure.



- Return the hoop to the machine.
- Stitch Machine Step 2, Cut Line and Tackdown.





STEP 5

- Remove the hoop from the machine, but NOT the project from the hoop.
- Place the hoop on a flat surface.
- Trim the excess fabric as close to the cut line at the top of the stocking as possible.




- Return the hoop to the machine.
- Match bobbin to top thread.
- Stitch Machine Step 3, Lace Detail.
- Stitch Machine Step 4, Gold Detail.






STEP 7

 Stitch Machine Step 5, Back Fabric Placement Stitch.
 Note: Guides provided at the top of the stockings for the folded fabric edge.




STEP 8

- Remove the hoop from the machine, but NOT the project from the hoop.
- Place the hoop on a flat surface.
- Align the folded edge of the back panel with the two guidelines at the top of the stocking.
- Tape in place to secure.
 Note: The fabric side with the Fusible Woven attached needs to be facing down.



- Return the hoop to the machine.
- Stitch Machine Step 6, Seam Stitch.





STEP 10

- Remove the hoop from the machine and the project from the hoop.
- Trim close to the Seam Stitch.
- Rinse in warm running water to remove the stabilizer.
- Let dry.



- Turn right side out.
 Tip: Use an Expert Point and Press Tool to help push out the curved edges.
- Press on a Perfect Embroidery Press Cloth.

