## **Product Usage Instructions**

## **Ultra Clean and Tear Fusible**

## **TearAway Stabilizer**

- Cut the Ultra Clean and Tear Fusible stabilizer approximately 2" larger than your hoop.
- Lay the item to be embroidered wrong side up on an ironing board.
- Place Ultra Clean and Tear Fusible, shiny side down, on the wrong side of item, centering over the area to be embroidered.
- Press the Ultra Clean and Tear Fusible with a medium iron, additional layers may be fused if necessary.
- Center the design area of the item to be embroidered over the center of the hoop.
- Hoop the item without pulling, making sure the stabilizer fills the hoop.
- Embroider the item.
  - HINT: A topping such as StitcH2O or Heat2Go should be on most embroidery, especially if the fabric has a nap or pile.

## **REMOVAL INSTRUCTIONS:**

- Remove your embroidered item from the hoop.
- Carefully peel the excess Ultra Clean and Tear Fusible from the fabric around the embroidered area until you reach the edges of the stitching.
- Tear the stabilizer carefully away from the embroidery, supporting the embroidery stitches between your thumb and finger to avoid distorting the embroidery or tearing out fragile stitches. If the stabilizer does not easily release, heat with a medium iron to release the fusible adhesive.
- Any remaining exposed stabilizer will disintegrate with laundering, but will remain under the stitches to add support to the design.

